


Machine mounts fail safe


type Triflex

Art.Code	L (mm)	Ls (mm)	K (mm)	H (mm)	B (mm)	BS (mm)	M (mm)	d1 (mm)	d2 (mm)	d3 (mm)	Sh A
PC140045	184	140	75	50	75	-	M16i	13	20	30	45°
PC140055	184	140	75	50	75	-	M16i	13	20	30	55°
PC140065	184	140	75	50	75	-	M16i	13	20	30	65°
PC140075	184	140	75	50	75	-	M16i	13	20	30	75°
4M16x110VERZ	Height adjustable spindle M16 x 110 complete										

L = length
Ls = spacing mounting holes
K = diameter lid
D = diameter
H = height
B = width
M = screw thread
d1 = bore diameter width
d2 = bore diameter length
d3 = bore diameter length
 Shore A = hardness



Load Fz



Ratio horizontal stiffness
Cx (longitudinal) and *Cy*
 (transverse direction) compared
 to *Cz* (load direction)
Cz : *Cx* : *Cy*
 1 : 2,7 : 0,7

