


Machine mounts fail safe


type Triflex

Art.Code	L (mm)	Ls (mm)	K (mm)	H (mm)	B (mm)	BS (mm)	M (mm)	d1 (mm)	d2 (mm)	d3 (mm)	Sh A
PC182045	230	182	112	70	112	-	M20i	18	26	34	45°
PC182055	230	182	112	70	112	-	M20i	18	26	34	55°
PC182065	230	182	112	70	112	-	M20i	18	26	34	65°
PC182075	230	182	112	70	112	-	M20i	18	26	34	75°
4M20x150VERZ	Height adjustable spindle M20 x 150 complete										

L = length
Ls = spacing mounting holes
K = diameter lid
D = diameter
H = height
B = width
M = screw thread
d1 = bore diameter width
d2 = bore diameter length
d3 = bore diameter length
Sh A = hardness



Load Fz



Ratio horizontal stiffness
 Cx (longitudinal) and Cy
 (transverse direction) compared
 to Cz (load direction)
 Cz : Cx : Cy
 1 : 2,6 : 0,85

